



Activity / Equipment:	Mobile Photo Booth	Date of Assessment:	30/12/2013
Assessed by:	Rob Lancaster	Date of Review:	30/12/2014

## RISK ASSESSMENT

HAZARD	OUTCOME / INJURY	PERSONS AT RISK	SEVERITY	PROBABILITY	RATING	EXISTING CONTROLS	FURTHER ACTION
Electrocution	Death, serious injury	Users, Operators, Spectators, Passers By	<b>4</b>	<b>1</b>	<b>4</b>	All electrical equipment to be regularly checked PAT and results recorded. Service checks to be completed on a monthly basis	None
Structural collapse	Death, serious injury	Users, Operators, Spectators, Passers By	<b>3</b>	<b>1</b>	<b>3</b>	Daily safety checks to be completed after each installation. Installation to be done by trained personnel only	None